



NOTE:  
 COLOUR CODE MATCHES STANDARD DCC  
 for MOTOR & SUPPLY (EXCEPT 3 POT WIRES).

TO RESET FUSE IF IT TRIPS OUT,  
 SWITCH POWER OFF FOR A FEW SECONDS.

IF MODEL WAS PREVIOUSLY TRACK POWERED  
 MOTOR + WAS JOINED TO RIGHT RAIL.

**WIRING DIAGRAM**

**KEN POVEY  
 PRODUCTION  
 ENGINEERS.**  
 Tel. : 01769 560127  
 Fax. : 01769 560016  
 Email: ken.povey@tiscali.co.uk

DRAWN. KEN POVEY 14 JUNE 07	DIMS IN. NA. SCALE. NA	TOLERANCES. NA UNLESS OTHERWISE STATED.	MATERIAL.	TITLE. <b>PWM SPEED          CONTROL WIRING</b>	No. of SHEETS <b>1 of 1</b>	DRAWING No. <b>SDCONPWM.SKD</b>	SHEET No. ISSUE	14 JUN 2007 ISSUE DATE
FINISH.	CHECKED.	CUSTOMER.						